


| | | |
|--|--|--|
| Search Notes  | Application/Control No. 10520337 | Applicant(s)/Patent Under Reexamination THYBO ET AL. |
| | Examiner Koca, Huseyin | Art Unit 3744 |

| | | | |
|-----------------|--------------------|-------------|-----------------|
| SEARCHED | | | |
| Class | Subclass | Date | Examiner |
| 62 | 127, 129, 222, 225 | 9/19/2007 | HK |

| | | |
|-------------------------------------|-------------|-----------------|
| SEARCH NOTES | | |
| Search Notes | Date | Examiner |
| Marc Norman was consulted | 9/26/2007 | HK |
| Frantz Jules was consulted | 9/26/2007 | HK |
| Inventor Name Search | 9/26/2007 | HK |
| (determin\$4 with flash with gas) | 9/19/2007 | HK |
| (fault with indiator) same residual | 9/26/2007 | HK |

| | | | |
|----------------------------|-----------------|-------------|-----------------|
| INTERFERENCE SEARCH | | | |
| Class | Subclass | Date | Examiner |
| | | | |